

Bluetooth Module Firmware Update Procedure

Precautions

- Update file is different by model. Refer to <Target Models> for the models which update is necessary.**
- Use the USB flash memory as the update media.
- Update cannot be performed with Disc media (CD-R/RW or DVD-R/RW).
- Be sure to park the vehicle in a safe place before updating. Keep the engine running in order to prevent battery from running out.
- Do not turn off the engine or Navigation/Multimedia receiver power while updating. Update cannot be performed correctly and the Navigation/Multimedia receiver may become unusable.

Note: Please be advised that the settings on Your Navigation/Multimedia receiver will be cleared further to completing the Software Update, i.e. Paired Phones, User Settings, Voice Tags.

Introduction

- This document describes the procedure and precautions for upgrading the Bluetooth Module firmware to conform to your cell-phone.
 - If an error occurs while updating the firmware, the Bluetooth Module may become unusable.
- Be sure to read the following procedure and precautions carefully before updating the firmware.

Checking the Firmware of the Cell-phone

Make sure that the connecting cell-phone model is in [Supported Cell-phone Model List].

If you can use your cell-phone without problems at the moment, you need not update the firmware.

Target Models

This updater can be used to update the firmware of the following models.

DNX8120, DNX8220BT, DDX812, DDX8032BT, DDX8022BT, DDX8022BTY, DDX8032BTM

Work Flow

- | | |
|-------------|--|
| Preparation | Check the firmware version and the connecting cell-phone model to check whether firmware update is required. |
| Step1 | Download the firmware Update File and copy it to the USB Thumb Drive. |
| Step2 | Updating the Program |
| Step3 | Check that the firmware has been updated. |

Checking the Firmware Version

1 Display the Source Select screen

Press the [SRC] button.

2 Select the STANDBY

Press the [STANDBY] button.



3 Enter Setup Menu

Press the [SETUP] button.



4 Display the Software Information screen

Press the [Software Information] button.



5 The firmware version appears



Step1: Before You Get Started

1 Insert a USB Thumb Drive into an available USB port on your computer.

Please copy and paste the following link:

<http://www.kenwood.com/bt/support/groupA/eng.html>

3 Copy the Update File to the Root Directory of the USB Thumb Drive.



4 Close the file and remove the USB Thumb Drive from your computer.

Step2: Updating the Program

1 Insert the USB Thumb Drive into the USB Cable

Note: Do not insert the USB Thumb Drive into the USB port labeled iPod.

2 Select the STANDBY

2-1 Press the [SELECT] button.

2-2 Press the [STANDBY] button.



3 Enter Setup Menu

Press the [SETUP] button.



4 Display the Software Information screen

Press the [Software Information] button.



Bluetooth Module Firmware Update Procedure

5 Starting the Update

Press the [Start] button.



Caution: The screen may go blank for a few seconds.

Do not unplug the USB Thumb Drive or Power Off the unit during the Update Procedure.

6 System Reboot & Software Update Screens

When "Waiting . . ." is displayed, "Now Updating" is also displayed.

7 Once the "Update Completed" screen is displayed, remove the USB Thumb Drive and restart the unit.

Note: This will require you to turn the vehicle ignition to the OFF position.

Caution: PIN code is changed to "1234". Set the PIN code again at "PIN EDIT" /"PIN Code Edit" in the Menu.

Step3: Verify the Bluetooth Firmware Version

Verify that the Firmware Version has been updated successfully in the Kenwood unit.

Refer to <Checking the Firmware Version> (page 1).

Your Kenwood unit now includes the necessary firmware version.

Troubleshooting Instructions

If the Update file is corrupted

If the following "Update file error!!" is displayed, the firmware updater file which is copied to the USB thumb drive may be corrupted. Perform the update procedure from the <Creating the Update Media> again.