

KENWOOD

Listen to the Future

Bluetooth Module Software Update Procedure


DNX8120 & DDX812 Bluetooth SW Update using USB Thumb Drive (Part 3)

Note: The USB Thumb Drive update is **ONLY** for the DNX8120 & DDX812 units.

This process will take approximately 4 minutes.

Download the USB Update File from the Kenwood website.

Copy the Update File to the Root Directory of the USB Thumb Drive.



USB Update Procedure



Insert the USB Thumb Drive into the USB Cable of the DNX8120.

Note: Do not insert the USB Thumb Drive into the USB port labeled iPod. Use the secondary USB port.

The DNX8120 / DDX812 will automatically change the Source from Standby to USB.

Starting the Update Procedure

Important: You will need to change the Source from USB to Standby.



Access the Software Information screen by selecting [SETUP] / [Software Information] from the menu. Press the [Start] button displayed next to the Version information.

Caution: Do not unplug the USB Thumb Drive during the Update Procedure.



"Now File Checking" will be displayed.

Note: Please be patient with the update process at this stage.


This screen may be displayed for 1 min.

System Reboot & Software Update Screens



Once the “Update Completed” screen is displayed, remove the USB Thumb Drive and restart the unit.

Verify the Bluetooth Software Update



From the Menu list, select [SETUP] then select [Software Information]. Verify that SW Version 1.60 has been updated successfully in the Kenwood unit.